




FOOD DIVISION

Zep Egg Washing Area Cleaning Procedures

Item To Be Cleaned		Customer: HICKMANS	Date: 01-16-13
Egg Washer		Address:	Procedure #:
		City, State, Zip Code:	
		Production Area	
		Egg Washing area Cleaning Procedures	
		<ol style="list-style-type: none"> 1. Dry Pick-Up all debris and large items from the floors and the egg washing machine surrounding area. 2. Pre-Rinse the walls and floors, including the floors underneath the egg washing machine and the drains, with water (120 - 140 F). 3. Foam or Spray the walls and floors, including the floors under the egg washer and the drains with a solution of Process Cleaner at a rate of 2 -4 oz. per gallon of water. 4. Allow the foam to stand on the surfaces for approximately 5 minutes before rinsing (DO NOT ALLOW THE FOAM TO DRY). 5. Rinse the walls and the floors thoroughly with potable water and allow it to air dry. 6. Inspect the area for cleanliness and re-clean if necessary. 	
Chemical Name	Concentration		
Process Cleaner	2 - 4 oz / gal		
Cleaner/Sanitizer Temperatures			
Foaming Cleaners	120 - 140 °F		
Cleaning Frequency			
Washer area cleaning	Daily		
Test Kits Required			
Process Cleaner 9438 Test Kit			
Application Equipment & Tools			
Foaming Units or Spray Bottles			
Safety Equipment	Required?		
Goggles/Face Shield	Yes		
Gloves	Yes		
Rubber Boots	Yes		
Rubber Apron	Yes		
Safety Precautions			
Always wear proper safety protection. Never add water to chemicals. Always add chemical to water. Report all accidents immediately!!			
Zep Inc.			
Service Representative			
Paul Piunti 480 577-6349			
Customer Service Center		Revision Date:	
1-877-428-9937		Sanitation Manager:	